Town Council*	Cleanliness	Maintenance	ARD Failure		Arrears	
Town Council	Gicariiiiooo	Maintonario				Amount in Arrears
Aljunied	Level 1	Level 3	Level 1	Level 1	Level 1	Level 1
Ang Mo Kio- Yio Chu Kang	Level 1	Level 2	Level 1	Level 1	Level 1	Level 1
Bishan-Toa Payoh	Level 1	Level 2	Level 1	Level 1	Level 2	Level 2
East Coast	Level 2	Level 3	Level 1	Level 1	Level 1	Level 1
Holland-Bukit Panjang	Level 1	Level 3	Level 1	Level 1	Level 1	Level 1
Hong Kah	Level 2	Level 3	Level 1	Level 1	Level 1	Level 1
Hougang	Level 2	Level 4	Level 2	Level 1	Level 5	Level 5
Jalan Besar	Level 1	Level 3	Level 1	Level 1	Level 1	Level 1
Jurong	Level 2	Level 3	Level 1	Level 1	Level 1	Level 1
Marine Parade	Level 1	Level 3	Level 1	Level 1	Level 1	Level 1
Pasir Ris-Punggol	Level 2	Level 3	Level 1	Level 1	Level 1	Level 1
Potong Pasir	Level 3	Level 5	Level 1	Level 1	Level 5	Level 5
Sembawang	Level 1	Level 2	Level 1	Level 1	Level 1	Level 1
Tampines	Level 2	Level 3	Level 1	Level 1	Level 1	Level 1
Tanjong Pagar	Level 1	Level 2	Level 1	Level 1	Level 1	Level 1
West Coast	Level 1	Level 3	Level 1	Level 1	Level 1	Level 1

^{*} Please click on the respective Town Council to view the breakdown of cleanliness and maintenance observations for their 2nd TCMR results.

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

National level

Type of Cleanliness Observations	% of Total Observations
Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	47%
Dumped bulky refuse	39%
Stain/litter found on floor	13%
Others	1%
Total	100%

Type of Maintenance Observations	% of Total Observations
Obstruction of common areas	18%
Unauthorised structures	10%
Damaged plaster/large cracks/spalling concrete/peeling paint work	8%
Corroded/stained/leaked mossy pipes/taps, unlocked taps	6%
Damaged/exposed/unlocked wiring/trunking/socket outlet	6%
Others	52%
Total	100%

To see photos of cleanliness and maintenance observations, please click here.

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

Town level

<u>Note</u>: Results are based on estate inspections conducted by HDB from Apr to Sep 2010. Under the "Cleanliness" indicator, the breakdown of observations may contain only 3 or 4 categories as the cleanliness observations recorded in the towns fall within the top 3 or 4 categories.

Aljunied Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	58%
2	Dumped bulky refuse	33%
3	Stain/litter found on floor	8%
4	Others	1%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	15%
2	Unauthorised structures	10%
3	Damaged plaster/large cracks/spalling concrete/peeling paint work	9%
4	Corroded/stained/leaked mossy pipes/taps, unlocked taps	8%
5	Damaged/exposed/unlocked wiring/trunking/socket outlet	5%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

Ang Mo Kio-Yio Chu Kang Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	56%
2	Dumped bulky refuse	36%
3	Stain/litter found on floor	7%
4	Others	1%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	23%
2	Damaged plaster/large cracks/spalling concrete/peeling paint work	9%
3	Corroded/stained/leaked mossy pipes/taps, unlocked taps	7%
4	Unauthorised structures	7%
5	Missing/defective/chipped floor/wall tiles	4%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

Bishan-Toa Payoh Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Dumped bulky refuse	48%
2	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	41%
3	Stain/litter found on floor	11%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	20%
2	Unauthorised structures	13%
3	Damaged plaster/large cracks/spalling concrete/peeling paint work	9%
4	Corroded/stained/leaked mossy pipes/taps, unlocked taps	5%
5	Missing/damaged gratings/floor traps	4%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

East Coast Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	50%
2	Dumped bulky refuse	36%
3	Stain/litter found on floor	14%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	17%
2	Unauthorised structures	11%
3	Corroded/stained/leaked mossy pipes/taps, unlocked taps	10%
4	Damaged/exposed/unlocked wiring/trunking/socket outlet	9%
5	Damaged plaster/large cracks/spalling concrete/peeling paint work	9%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

Holland-Bukit Panjang Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	45%
2	Dumped bulky refuse	43%
3	Stain/litter found on floor	11%
4	Others	1%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	20%
2	Unauthorised structures	10%
3	Corroded/stained/leaked mossy pipes/taps, unlocked taps	8%
4	Damaged plaster/large cracks/spalling concrete/peeling paint work	7%
5	Damaged/exposed/unlocked wiring/trunking/socket outlet	7%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

Hong Kah Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	53%
2	Dumped bulky refuse	33%
3	Stain/litter found on floor	14%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	16%
2	Unauthorised structures	12%
3	Damaged plaster/large cracks/spalling concrete/peeling paint work	8%
4	Corroded/stained/leaked mossy pipes/taps, unlocked taps	5%
5	Damaged/exposed/unlocked wiring/trunking/socket outlet	5%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

Hougang Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	45%
2	Dumped bulky refuse	37%
3	Stain/litter found on floor	17%
4	Others	1%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	13%
2	Damaged plaster/large cracks/spalling concrete/peeling paint work	10%
3	Unauthorised structures	9%
4	Corroded/stained/leaked mossy pipes/taps, unlocked taps	8%
5	Damaged staircase risers, treads/nosings	5%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

Jalan Besar Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	47%
2	Dumped bulky refuse	37%
3	Stain/litter found on floor	15%
4	Others	1%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	18%
2	Unauthorised structures	11%
3	Damaged plaster/large cracks/spalling concrete/peeling paint work	8%
4	Corroded/stained/leaked mossy pipes/taps, unlocked taps	7%
5	Damaged/exposed/unlocked wiring/trunking/socket outlet	6%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

Jurong Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	57%
2	Dumped bulky refuse	31%
3	Stain/litter found on floor	12%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	16%
2	Unauthorised structures	11%
3	Damaged plaster/large cracks/spalling concrete/peeling paint work	10%
4	Corroded/stained/leaked mossy pipes/taps, unlocked taps	8%
5	Plants/weeds growing on walls, joints, pipes and gutters	4%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

Marine Parade Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Dumped bulky refuse	44%
2	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	42%
3	Stain/litter found on floor	14%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	16%
2	Unauthorised structures	10%
3	Damaged/exposed/unlocked wiring/trunking/socket outlet	8%
4	Damaged plaster/large cracks/spalling concrete/peeling paint work	7%
5	Corroded/stained/leaked mossy pipes/taps, unlocked taps	6%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

Pasir Ris-Punggol Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Dumped bulky refuse	44%
2	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	40%
3	Stain/litter found on floor	15%
4	Others	1%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	19%
2	Unauthorised structures	10%
3	Damaged/exposed/unlocked wiring/trunking/socket outlet	7%
4	Damaged plaster/large cracks/spalling concrete/peeling paint work	7%
5	Defective/damaged refuse hoppers	6%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

Potong Pasir Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Dumped bulky refuse	41%
2	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	36%
3	Stain/litter found on floor	22%
4	Others	1%

	Type of Maintenance Observations	% of Total Observations
1	Damaged/exposed/unlocked wiring/trunking/socket outlet	10%
2	Obstruction of common areas	10%
3	Damaged plaster/large cracks/spalling concrete/peeling paint work	7%
4	Missing/damaged gratings/floor traps	7%
5	Unauthorised structures	6%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

Sembawang Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	48%
2	Dumped bulky refuse	38%
3	Stain/litter found on floor	14%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	25%
2	Unauthorised structures	11%
3	Damaged plaster/large cracks/spalling concrete/peeling paint work	6%
4	Corroded/stained/leaked mossy pipes/taps, unlocked taps	5%
5	Damaged/exposed/unlocked wiring/trunking/socket outlet	4%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

Tampines Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	42%
2	Dumped bulky refuse	42%
3	Stain/litter found on floor	16%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	17%
2	Unauthorised structures	11%
3	Corroded/stained/leaked mossy pipes/taps, unlocked taps	8%
4	Damaged plaster/large cracks/spalling concrete/peeling paint work	8%
5	Damaged/exposed/unlocked wiring/trunking/socket outlet	6%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

Tanjong Pagar Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	46%
2	Dumped bulky refuse	42%
3	Stain/litter found on floor	11%
4	Others	1%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	19%
2	Unauthorised structures	11%
3	Damaged plaster/large cracks/spalling concrete/peeling paint work	7%
4	Corroded/stained/leaked mossy pipes/taps, unlocked taps	4%
5	Damaged/exposed/unlocked wiring/trunking/socket outlet	4%

2nd TCMR: Breakdown of cleanliness and maintenance observations (up to top 5 categories)

West Coast Town Council

	Type of Cleanliness Observations	% of Total Observations
1	Graffiti/stain/moss/cobwebs on walls/ceilings/fittings etc	49%
2	Dumped bulky refuse	38%
3	Stain/litter found on floor	12%
4	Others	1%

	Type of Maintenance Observations	% of Total Observations
1	Obstruction of common areas	16%
2	Unauthorised structures	8%
3	Corroded/stained/leaked mossy pipes/taps, unlocked taps	8%
4	Damaged plaster/large cracks/spalling concrete/peeling paint work	7%
5	Damaged/exposed/unlocked wiring/trunking/socket outlet	6%

Back to Main Page

Note: All figures are rounded to the nearest percentage. The top five observations shown do not represent all observations found during inspection.