





Wall in its clean state



Central refuse chute area dumped with refuse

Central refuse chute area free of dumping



Stain on staircase

Staircase in its clean state

Examples of Estate Cleanliness Observations



Litters in apron drain

Apron drain free from litter



Cobwebs on light fitting

Light fitting in its clean state

Examples of Estate Maintenance Observations



Dangling ceiling light fitting

Light fitting firmly affixed to ceiling



Corroded staircase railings

Staircase railings in good condition



Obstruction of corridor

Corridor free from obstruction

Examples of Estate Maintenance Observations



Unauthorised clothes drying rack erected at corridor

Corridor without any unauthorised structure



Spalling concrete on corridor ceiling

Corridor ceiling in good condition